



...connecting to the aftermarket

Vehicle Setting Matrix for MOST iPod interface

Known Issues

- 1) BMW E65/E66 trackdownload in latest BMW software disc B29 load correctly
- 2) Audi MMI on fast startup automatically tries to select a disc. Connects2 returns an error which the MMI does not accept. Fix will be contained in next software version 3.2.0

Make	Vehicle's System / Headunit Type	Years	Vehicle Setting	Folder setting
Audi	MMI	04 - current	audi	folder
BMW	iDrive (2002-2004 non-Nav)	02 - 04	bmw-nonmp3	numbered
	iDrive (2004+ with Nav, not 7-ser.)	04 - current	bmw	folder
	iDrive (late-2005+ 7-series)	05 - current	bmw	folder
	non-iDrive, "Professional" Radio	06 - current	bmw	numbered
Mercedes-Benz	COMAND (color screen type)	04 - current	mb	folder
	Audio20 (Green dot-matrix disp.)	04 - current	mb	numbered
	Audio50 (color mini-screen)	03 - current	mb	numbered
MINI (non-convertible)	Radio (red display)	06 - current	mini	numbered
	Navigation	06 - current	mini	folder
Porsche	CDR23 / 24 ("base radio")	03 - current	porsche	numbered
	PCM (2.0/B/2.1/A/B)	03 - current	porsche	folder
SAAB	ICM2 (green screen) front CDC	03-06	saab	folder
	ICM3 (color screen) Front CDC	03-06	saab	folder
	ICM2 (green screen) rear CDC	03-06	saabrear	folder
	ICM3 (color screen) rear CDC	03-06	saabrear	folder